

ADVISORY NOTICE

01_2026_ECL 760_new software version sw 2.3e

Dear customers,

We hereby inform you that the ECL 760 device software has been updated to SW version 2.3e.

1. Purpose: Bug fix

2. List of changes in Application Software ver. 2.3e:

- Bug fix - the reagents cannot setup in the reagent position after scan the reagent cards.

If you have software version 2.2e installed on your device and you are experiencing an issue with saving reagents to their positions after scanning reagent cards, please update the software to version 2.3e. For devices with the original software version 2.2e, this issue was already resolved during manufacturing.

SW version 2.3e is already included in devices produced from SN 0452-71-100225.

For SW version 2.3e, please contact your local service engineer or distributor. The latest version of the SW is available on the [ERBA Knowledge Base](#) website.

Applied for:

INSTRUMENTS:

10020477	INS00070	ECL 760
----------	----------	---------

In case you have any additional questions, please do not hesitate to contact us.

Best regards,
Erba Lachema s.r.o.

Erba Lachema s.r.o.
Karásek 2219/1d, 621 00 Brno
DIČ: CZ26918846 -7-



Brno, 20th January 2026

Ref. No.AN_01_2026